

~~Annexure~~ ✓ File

**GOVERNMENT OF WEST BENGAL**  
**OFFICE OF THE DIVISIONAL FIRE OFFICER**  
**WEST BENGAL FIRE & EMERGENCY SERVICES**  
Sepoy Bazar, P.O. - Midnapore, P.S. - Kotwali, Pin -  
721101

Memo No : IND/WB/FES/20182019/13784

DATE: 26/11/2018

From :  
The Divisional Fire Officer  
Fire Prevention Wing,  
West Bengal Fire & Emergency Services.

To :  
RANAJIT KUMAR PAL  
ANANDAM HSPMI  
Midnapur F.S., Garbeta,  
Paschim Medinipur - 721121 .

Sub : Fire Safety Certificate for the occupancy of an existing construction of G +2 storied building under group Educational at the premises no.- ANANDAM H.S PAL INSTITUTE AT-TALDANGRA,P.O-AMLAGORA P.S-GARHBETA, DIST-PASCHIM MEDINIPORE - 721121

This is in reference to your Application No. IND/WB/FES/20182019/13784, dated 26/11/2018, regarding the Fire Safety Certificate for the occupancy of an existing construction of G +2 storied building under group Educational at the premises no.- ANANDAM H.S PAL INSTITUTE AT-TALDANGRA,P.O-AMLAGORA P.S-GARHBETA, DIST-PASCHIM MEDINIPORE - 721121.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Fire Safety Certificate for occupancy of the aforesaid building.

However to up-keep the Fire Safety Measure of the aforesaid building the following safety measures need to be incorporated / maintained.

1. This is reference to your Application No - IND/WB/FES/20182019/17384 dated-

*Janardan Pal*  
Secretary  
**ANANDAM**  
(H.S. Paul Memorial Institute)  
Taldangra, Fatesingpur  
Paschim Medinipur, 721121

*Attested  
Deputy Fire Officer  
26/11/18*

14/11/2018 regarding the Fire Safety Certificate of above mention address.

The performance of the Fire Fighting System as incorporated in the building were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Fire Safety Certificate for occupancy of the aforesaid building.

However to keep-up the Fire Safety Measure of the aforesaid building the following safety measure need to incorporated/maintained.

1. Drive away must be free from any type of obstruction for easy movement of Fire Appliances. No parking shall be allowed on the drive away.
2. Directional sign and escape route shall be displayed prominently.
3. The interior finish decoration of the building shall be made with low flame spread materials conforming to IS specification.
4. To eliminate risk of the fire hazards, good house keeping both for inside and outside of the building shall be maintained.
5. Existing electrical wiring of the whole building shall have to be carefully checked for anywhere and tear in them, particularly lines above false ceiling and ducts.
6. A fire control room including a close circuit T.V. system will have to be maintained which all floor of the building.
7. The Notice of fire Fighting and evacuation with "EXIT SIGN" from the building shall be prepared and displayed at all vulnerable of the building.
8. The employee and security staff shall be conversant with installed Fire fighting equipments of the building and to operate in the event of fire and testing.
9. Mock Fire practice and Evacuation Drill shall be performed with all participants at regular interval.
10. Transformer and switch gear room shall be protected with automatic CO-2 or DCP Fire Extinction conforming I.S. specification.
11. A crew of trained Fireman under an experienced officer shall be maintained round the clock basis.
12. First Aid fire fighting system shall be provided as per I.S. specification.
13. Arrangement shall have to be made for regular checking, testing, and maintenance of all the Fire Fighting installation in the building to keep them in perfectly good working condition at all the times.
14. If required the old line shall have to be replace with new lines the cable shall always be laid in M.S. conduct pipes continuously bonded to the earth.
15. The Fire Safety Audit to be conducted a regular interval and to be recorded to the Fire Prevention maintenance regular.
16. This FSC is valid for one year and have to be renewed ever year from the date of issue of this letter.
17. Each year a Certificate is to be obtained from the Divisional Fire officer Paschim Medinipur Division, West Bengal Fire & Emergency Services performance of all the life & Fire safety arrangement and installation of the building.

*Janardan Pal*

Secretary  
ANANDAM  
(H.S. Paul Memorial Institute)  
Taldangra, Fatesingpur,  
Paschim Medinipur, 721121



18. Periodical flashing of the water from the hydrants and Hose reel Hose pipe Line shall be made to maintain the efficient working performance of the above mentioned system.
19. No Addition & Alteration without prior permission of West Bengal Fire & Emergency Services, Otherwise The Fire Safety Certificate will be treated as cancelled.

Divisional Fire Officer  
Paschim Medinipur

Division

West Bengal Fire &

Emergency Services.

Divisional Fire Officer  
West Bengal Fire & Emergency Services

*Janardan Pal*

Secretary  
AMANDAM  
(H.S. Paul Memorial Institute)  
Taldara, Pattingpur  
Paschim Medinipur, 721121

Validity unknown

Digitally signed by RATAN  
KUMAR HALDER  
Date: 2018.11.26 14:00:07 IST

*A. K. Halder*  
*Ratan Kumar Halder*  
*26/11/18*





Government Of West Bengal  
Office Of The Divisional Fire Officer, Paschim Medinipur  
West Bengal Fire & Emergency Services  
Sepoy Bazar, P.O.: - Medinipur, P.S.: - Kotwali, Pin:- 721101

Memo no.: IND/WB/FES/20182019/13784

Date: 26-06-2021

**From:**  
Divisional Fire Officer, Paschim Medinipur  
West Bengal Fire & Emergency Services

**To:** RANAJIT KUMAR PAL, ANANDAM H.S PAUL MEMORIAL INSTITUTE.  
VILL - TALDANGRA, FATESINGPUR,, POST - AMLAGORA, PS - GARHBETA, DIST - PASCHIM MEDINIPUR, PIN - 721121

**Sub:** Renewal of Fire Safety Certificate for the occupancy of an existing construction of G+II storied building name & style of ANANDAM H.S PAL MEMORIAL INSTITUTE under group of Educational Building at the premises Mouza – Taldangra Khasjungle, J.L. No. – 478, P.S. – Garhbeta, Dist – Paschim Medinipur.

This is in reference to your application no. 0125191211500019 dated 12-05-2021 regarding the Renewal of Fire Safety Certificate for the occupancy of an existing construction of G+II storied building name & style of ANANDAM H.S PAL MEMORIAL INSTITUTE under group of Educational Building at the premises Mouza – Taldangra Khasjungle, J.L. No. – 478, P.S. – Garhbeta, Dist – Paschim Medinipur.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Renewal of Fire Safety Certificate for occupancy of the aforesaid building.

However to up-keep the Fire Safety Measure of the aforesaid building the following safety measures need to be incorporated / maintained.

**Recommendation:**

1. Driveway must be free of any type of obstruction for EASY movement of Fire Appliances. No perking will be allowed on the driveway.
2. Directional sign and escape route shall be displayed prominently.
3. To eliminate risk of Fire Hazards, Good House Keeping both for insides and outside of the building shall be strictly maintained.

**Principal**  
**ANANDAM**  
(H.S. Paul Memorial Institute)  
Taldangra, Fatesingpur  
Paschim Medinipur, 721121



4. The interior finish decoration of building shall be made with low flame spread material confirming I.S. Specification.
5. The notice of Fire Fighting and Evacuation with "Exit Sign" from the building shall be prepared and displayed at all vulnerable places of the building.
6. The employees and security staff shall be conversant with installed Fire Fighting equipment of the building and to operate in the event of Fire and Testing
7. Mock Fire practice and evacuation drill shall be performed periodically with participation of all occupants of building.
8. First – Aid Fire Fighting system shall be provided as per I.S Specification.
9. Arrangement shall have to be made for regular checking, testing, and maintenance of all the Fire Fighting installation in the Building to keep them in perfectly good working condition at all the times.
10. If required the old line shall have to be replaced with new line the cables shall always be laid in M.S. conduit pipes continuously bounded to the earth.
11. Periodical flashing of water from the Hydrants pipe line shall be made to maintain the efficient working performance of above mentioned system.
12. The Fire Safety audit to be conducted at regular interval and to be recorded in the Fire Prevention maintenance register.
13. Existing Electrical wiring of the whole building shall have to be carefully checked for anywhere and tear in them, particularly lines above false ceiling and ducts.
14. A Fire control room with close circuit T.V. system will have to be installed which will observe all the floor of the building.
15. Transformer and Switch Gear room shall be protected with automatic CO2 or D.C.P. Fire extinguisher conforming I.S. Specification.
16. Under Ground Water Reservoir Capacity 20000ltrs for fire-fighting purpose shall be constructed within 60 days from receipt of this R F S C
17. This Renewal Fire Safety Certificate is valid for three year and has to be renewed every three year from the date of issue of this letter.
18. Each three year a certificate is to be obtained from the Director General, West Bengal Fire & Emergency Services, performance of all the Life & Fire Safety arrangements and installation of the building.

N.B: No addition and alteration without prior permission of West Bengal Fire & Emergency Services. Otherwise the Fire Safety certificate will be treated as cancelled.



Signature Not Verified  
Signed by: TAPTI KUMAR BANERJEE  
Position: Approved  
Location: West Bengal  
Date: 26-Jun-2021 12:47:12

Divisional Fire Officer, Paschim Medinipur  
West Bengal Fire & Emergency Services

Memo No.: IND/WB/FES/20182019/13784